

A 236068

Address of Well Location (Street Number/Name) 17 Barrie Terr		Township ORO medonte	Lot 1	Concession 1
County/District/Municipality Simcoe		City/Town/Village	Province Ontario	Postal Code
UTM Coordinates Zone NAD 83	Easting 17608198	Northing 4916498	Municipal Plan and Sublot Number	Other

Overburden and Bedrock Materials/Abandonment Sealing Record (see instructions on the back of this form)				
General Colour	Most Common Material	Other Materials	General Description	Depth (m/ft) From To
Brown	sand	clay	mixed	0 8
Brown	clay			8 15
grey	clay			15 46
grey	clay	sand	mixed	46 74
Brown	sand	clay	Mixed - Fine to med	74 86

Annular Space		
Depth Set at (m/ft) From To	Type of Sealant Used (Material and Type)	Volume Placed (m³/ft³)
0 22	Bentonite	28 ft³

Method of Construction	Well Use
<input checked="" type="checkbox"/> Cable Tool <input type="checkbox"/> Rotary (Conventional) <input type="checkbox"/> Rotary (Reverse) <input type="checkbox"/> Boring <input type="checkbox"/> Air percussion <input type="checkbox"/> Other, specify _____	<input type="checkbox"/> Public <input checked="" type="checkbox"/> Domestic <input type="checkbox"/> Livestock <input type="checkbox"/> Irrigation <input type="checkbox"/> Industrial <input type="checkbox"/> Other, specify _____

Construction Record - Casing				Status of Well	
Inside Diameter (cm/in)	Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel)	Wall Thickness (cm/in)	Depth (m/ft)		<input checked="" type="checkbox"/> Water Supply <input type="checkbox"/> Replacement Well <input type="checkbox"/> Test Hole <input type="checkbox"/> Recharge Well <input type="checkbox"/> Dewatering Well <input type="checkbox"/> Observation and/or Monitoring Hole <input type="checkbox"/> Alteration (Construction) <input type="checkbox"/> Abandoned, Insufficient Supply <input type="checkbox"/> Abandoned, Poor Water Quality <input type="checkbox"/> Abandoned, other, specify _____ <input type="checkbox"/> Other, specify _____
			From	To	
6 1/4	Steel	1 1/8	0	78	

Construction Record - Screen				
Outside Diameter (cm/in)	Material (Plastic, Galvanized, Steel)	Slot No.	Depth (m/ft)	
			From	To
5	Steel	12	78	82
5	Steel	8	82	86

Water Details		Hole Diameter	
Water found at Depth (m/ft)	Kind of Water: <input checked="" type="checkbox"/> Fresh <input checked="" type="checkbox"/> Untested <input type="checkbox"/> Gas <input type="checkbox"/> Other, specify _____	Depth (m/ft) From To	Diameter (cm/in)
86		0 22	10
		22 86	6

Well Contractor and Well Technician Information	
Business Name of Well Contractor Clearwater Drilling	Well Contractor's Licence No. 716 32
Business Address (Street Number/Name) 3524 Hwy 93 Barrie	Municipality Barrie
Province Ont	Postal Code L4M4Y8
Business E-mail Address	

Bus. Telephone No. (inc. area code) 705 728 9497	Name of Well Technician (Last Name, First Name) Prince Mark
Well Technician's Licence No. 2535	Signature of Technician and/or Contractor <i>[Signature]</i>
Date Submitted 20180608	

Results of Well Yield Testing				
After test of well yield, water was: <input checked="" type="checkbox"/> Clear and sand free <input type="checkbox"/> Other, specify _____	Draw Down		Recovery	
	Time (min)	Water Level (m/ft)	Time (min)	Water Level (m/ft)
If pumping discontinued, give reason: Static Level		16		
	1	17.6	1	25.4
Pump intake set at (m/ft) 86	2	19.9	2	23.9
	3	19.4	3	22.5
Pumping rate (l/min / GPM) 2	4	20.2	4	21.1
	5	21.1	5	20.3
Duration of pumping 3 hrs + _____ min	10	24.4	10	18.6
	15	25.7	15	17.7
Final water level end of pumping (m/ft) 27	20	26.2	20	16.1
	25	26.5	25	16
If flowing give rate (l/min / GPM)	30	26.7	30	16
	40	27	40	16
Recommended pump depth (m/ft) 70	50	27	50	16
	60	27	60	16
Recommended pump rate (l/min / GPM) 7	Well production (l/min / GPM) 8			
	Disinfected? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			

Map of Well Location
Please provide a map below following instructions on the back.

Comments:	Well owner's information package delivered <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Date Package Delivered 20180608	Date Work Completed 20180608
Ministry Use Only Audit No. 2271688 Received AUG 15 2018			